



269 WESTWOOD DR.



Committee of Adjustment









EAST ELEVATION

PRIVATE RESIDENCE

269 WESTWOOD DR. OAKVILLE








NORTH ELEVATION

PRIVATE RESIDENCE

269 WESTWOOD DR. OAKVILLE



Scale: 1" = 10'-0"


2022-04-20 10:39:51 AM




WEST ELEVATION

PRIVATE RESIDENCE

269 WESTWOOD DR. OAKVILLE








SOUTH ELEVATION

PRIVATE RESIDENCE

269 WESTWOOD DR. OAKVILLE



Scale: 1" = 10'-0"



Prepared for: Element Modern Dwellings

603 York St, Oakville, ON L6L 4B4 905-208-7771 brad@elementmoderndwellings.com

Project Address:

269 Westwood Drive, Oakville, Ontario DENG File # n/a

Data Collection and Report Prepared by:

Stephen Shelton ON-0542AT, TRAQ 1589 <u>steve@summitsks.ca</u> 25 April 2022

Table of Contents

Project Overview	3
Municipal Trees	3
Neighbouring Trees	4
Private Trees	4
Tree Data Graph	10
Author's Qualifications	16
Limitations of Assessment	17
Tree Preservation Plan	18

Summit SKS Limited have been retained by the property owner to prepare this Arborist Report and Tree Protection Plan for 269 Westwood Drive in Oakville, Ontario. The owner intends to demolish the existing house and build a new one. The tree assessment was completed on the 3rd day of March 2022. All field and appraisal work was conducted by qualified consultants as defined by the Town and in accordance with Private Tree Protection By-Law 2017-038. A Tree Protection Agreement will be required for this project.

The purpose of this report is to inventory and assess trees 10cm in diameter, measured at breast height and larger on the subject property, in the city road allowance adjacent to the property and any trees within 6m of the property line. The owner of this property intends to demolish the existing house and build a new one. There are forty-four (44) trees recommended for removal as a result of this proposed construction and/or their current condition.

Municipally Owned Trees

Tree number M1 is a 10, 21, 31cm dbh Cedar White that is growing on the municipally owned boulevard. This tree is in fair condition and requires a tree protection zone of 3m.

Tree number M2 is a 9, 11, 13, 13, 13cm dbh Cedar White that is growing on the municipally owned boulevard. This tree is in fair condition and requires a tree protection zone of 2.4m.

Tree number M3 is a 11, 13, 13, 14, 16cm dbh Cedar White that is growing on the municipally owned boulevard. This tree is in fair condition and requires a tree protection zone of 2.4m.

Tree number M4 is a 11, 14cm dbh Mulberry White that is growing on the municipally owned boulevard. This tree is in fair condition and requires a tree protection zone of 2.4m.



Tree Number		Diameter of Appraised Tree (cm)	Area Of Appraised		the Replacem ent Tree	Cost of Replacem ent Tree		Species Rating	Basic Value	Location Rating	Condition s Rating	Appraised Value
M1	White Cedar	35	961.625	6	28.26	630	22.29299	66.00%	14362.95	75.00%	70.00%	7540.54875
M2	White Cedar	18	254.34	6	28.26	630	22.29299	66.00%	3956.4	75.00%	70.00%	2077.11
МЗ	White Cedar	20	314	6	28.26	630	22.29299	66.00%	4834.2	75.00%	70.00%	2537.955
M4	White Mulberry	16	200.96	6	28.26	450	15.92357	43.00%	1632.5	60.00%	65.00%	636.675

Neighbouring Trees

Tree number N1 is a 22cm dbh Maple Norway that is growing on the front yard of 279 Westwood Court. This tree is in fair condition and requires a tree protection zone of 2.4m.

Tree number N2 is a 10 to 15cm dbh Elm Siberian hedge that is growing on the front yard of 279 Westwood Court. This tree is in poor condition and requires a tree protection zone of 2.4m.

Tree number N3 is a 21cm dbh Juniper that is growing on the front yard of 279 Westwood Court. This tree is in fair condition and requires a tree protection zone of 2.4m.

Tree number N4 is a 26, 38cm dbh Hemlock Eastern that is growing on the backyard of 1036 Rebecca Street. This tree is in fair condition and requires a tree protection zone of 3m.

Tree number N5 is a 46cm dbh Cherry Black that is growing on the backyard of 1036 Rebecca Street. This tree is in fair condition and requires a tree protection zone of 3m.

Tree number N6 is a 54cm dbh Cherry Black that is growing on the backyard of 1036 Rebecca Street. This tree is in fair condition and requires a tree protection zone of 3.6m.

Tree number N7 is a 45cm dbh Birch River that is growing on the backyard of 1028 Rebecca Street. This tree is in fair condition and requires a tree protection zone of 3m.

Tree number N8 is a 50cm dbh Beech American that is growing on the backyard of 1028 Rebecca Street. This tree is in fair condition and requires a tree protection zone of 3m.

Tree number N9 is a 60cm dbh Pine Eastern White that is growing on the backyard of 1020 Rebecca Street. This tree is in fair condition and requires a tree protection zone of 3.6m.

Tree number N10 is a 15cm dbh Cherry Black that is growing on the backyard of 1020 Rebecca Street. This tree is in fair condition and requires a tree protection zone of 2.4m.

Tree number N11 is a 20cm dbh Maple Red (soft maple) that is growing on the backyard of 1023 Lakeshore Road West. This tree is in fair condition and requires a tree protection zone of 2.4m.

Tree number N12 is a 15cm dbhSpruce White that is growing on the backyard of 1023 Lakeshore Road West. This tree is in fair condition and requires a tree protection zone of 2.4m.

Tree number N13 is a 20cm dbh Maple Red (soft maple) that is growing on the backyard of 1023 Lakeshore Road West. This tree is in fair condition and requires a tree protection zone of 2.4m.

Tree number N14 is a 40cm dbh Pine Eastern White that is growing on the backyard of 1023 Lakeshore Road West. This tree is in fair condition and requires a tree protection zone of 3m.

Tree number N15 is a 60cm dbh Butternut that is growing on the backyard of 1023 Lakeshore Road West. This tree is in fair condition and requires a tree protection zone of 3.6m. This tree will require genetic testing by a Butternut Assessor.

Tree number N16 is a 19cm dbh Maple Red (soft maple) that is growing on the backyard of 1023 Lakeshore Road West. This tree is in fair condition and requires a tree protection zone of 2.4m.

Tree number N17 is a 16cm dbhAsh White that is growing on the backyard of 259 Westwood Court. This tree is in poor condition and requires a tree protection zone of 2.4m.

Tree number N18 is a 20cm dbhBeech American that is growing on the backyard of 259 Westwood Court. This tree is in fair condition and requires a tree protection zone of 2.4m.

Tree number N19 is a 50cm dbh Pine Eastern White that is growing on the backyard of 259 Westwood Court. This tree is in fair condition and requires a tree protection zone of 3m.

Privately Owned Trees

Tree number P1 is a 58cm dbh Maple Norway that is growing on the front yard of the subject property. This tree is in poor condition and requires a tree protection zone of 3.6m.

Tree number P2 is a 101cm dbh Maple Sugar (hard maple) that is growing on the front yard of the subject property. This tree is in fair condition and requires a tree protection zone of 6m.

Tree number P3 is a 13, 15, 15, 20, 20cm dbh Yew Canada that is growing on the front yard of the subject property. This tree is in fair condition and requires a tree protection zone of 2.4m.

Tree number P4 is a 23cm dbh Beech American that is growing on the front yard of the subject property. This tree is in fair condition and requires a tree protection zone of 2.4m.

Tree number P5 is a 20cm dbh Beech American that is growing on the front yard of the subject property. This tree is in fair condition and requires a tree protection zone of 2.4m.

Tree number P6 is a 27cm dbh Beech American that is growing on the front yard of the subject property. This tree is in fair condition and requires a tree protection zone of 2.4m.

Tree number P7 is a 37cm dbh Apple that is growing on the front yard of the subject property. This tree is in poor condition however it is recommended for removal due to development impacts.

Tree number P8 is a 14, 14, 17, 76cm dbh Beech American that is growing on the front yard of the subject property. This tree is in fair condition however it is recommended for removal due to development impacts.

Tree number P9 is a 18, 19cm dbh Beech American that is growing on the front yard of the subject property. This tree is in fair condition and requires a tree protection zone of 2.4.

Tree number P10 is a 32cm dbh Beech American that is growing on the front yard of the subject property. This tree is in fair condition and requires a tree protection zone of 3m.

Tree number P11 is a 72cm dbh Maple Sugar (hard maple) that is growing on the front yard of the subject property. This tree is in fair condition and requires a tree protection zone of 4.8m.

Tree number P12 is a 64cm dbh Beech American that is growing on the front yard of the subject property. This tree is in poor condition and requires a tree protection zone of 4.2m.

Tree number P13 is a 62cm dbh Beech American that is growing on the front yard of the subject property. This tree is in fair condition and requires a tree protection zone of 4.2m.

Tree number P14 is a 57cm dbh Pine Eastern White that is growing on the front yard of the subject property. This tree is in fair condition however it is recommended for removal due to development impacts.

Tree number P15 is a 70cm dbh Beech American that is growing on the front yard of the subject property. This tree is in fair condition however it is recommended for removal due to development impacts.

Tree number P16 is a 20cm dbh Beech American that is growing on the backyard of the subject property. This tree is in fair condition however it is recommended for removal due to development impacts.

Tree number P17 is a 16cm dbh Beech American that is growing on the backyard of the subject property. This tree is in fair condition however it is recommended for removal due to development impacts.

Tree number P18 is a 15cm dbh Beech American that is growing on the backyard of the subject property. This tree is in fair condition however it is recommended for removal due to development impacts.

Tree number P19 is a 62cm dbh Beech American that is growing on the backyard of the subject property. This tree is in fair condition however it is recommended for removal due to development impacts.

Tree number P20 is a 16cm dbh Cherry Black that is growing on the backyard of the subject property. This tree is in poor condition however it is recommended for removal due to development impacts.

Tree number P21 is a 30cm dbh Cherry Black that is growing on the backyard of the subject property. This tree is in poor condition however it is recommended for removal due to development impacts.

Tree number P22 is a 26cm dbh Cherry Black that is growing on the backyard of the subject property. This tree is in poor condition however it is recommended for removal due to development impacts.

Tree number P23 is a 18cm dbh Beech American that is growing on the backyard of the subject property. This tree is in fair condition however it is recommended for removal due to development impacts.

Tree number P24 is a 62cm dbh Walnut Black that is growing on the backyard of the subject property. This tree is in fair condition and requires a tree protection zone of 4.2m.

Tree number P25 is a 31cm dbh Cherry Black that is growing on the backyard of the subject property. This tree is in poor condition and requires a tree protection zone of 3m.

Tree number P26 is a 24cm dbh Cherry Black that is growing on the backyard of the subject property. This tree is in fair condition and requires a tree protection zone of 2.4m.

Tree number P27 is a 32cm dbh Butternut that is growing on the backyard of the subject property. This tree is in poor condition and requires a tree protection zone of 3m.

Tree number P28 is a 17cm dbh Maple Norway that is growing on the backyard of the subject property. This tree is in fair condition and requires a tree protection zone of 2.4m.

Tree number P29 is a 22cm dbh Birch Yellow that is growing on the backyard of the subject property. This tree is in poor condition and requires a tree protection zone of 2.4m.

Tree number P30 is a 17cm dbh Maple Norway that is growing on the backyard of the subject property. This tree is in fair condition and requires a tree protection zone of 2.4m.

Tree number P31 is a 62cm dbh Pine Eastern White that is growing on the backyard of the subject property. This tree is in poor condition and requires a tree protection zone of 4.2m.

Tree number P32 is a 56cm dbh Pine Eastern White that is growing on the backyard of the subject property. This tree is in fair condition and requires a tree protection zone of 3.6m.

Tree number P33 is a 35cm dbh Maple Sugar (hard maple) that is growing on the backyard of the subject property. This tree is in fair condition and requires a tree protection zone of 3m.

Tree number P34 is a 28cm dbh Cherry Black that is growing on the backyard of the subject property. This tree is in fair condition and requires a tree protection zone of 2.4m.

Tree number P35 is a 16cm dbh Maple Norway that is growing on the backyard of the subject property. This tree is in fair condition and requires a tree protection zone of 2.4m.

Tree number P36 is a 26cm dbh Maple Norway that is growing on the backyard of the subject property. This tree is in fair condition and requires a tree protection zone of 2.4m.

Tree number P37 is a 41cm dbh Cherry Black that is growing on the backyard of the subject property. This tree is in fair condition and requires a tree protection zone of 3m.

Tree number P38 is a 20cm dbh Maple Norway that is growing on the backyard of the subject property. This tree is in fair condition and requires a tree protection zone of 2.4m.

Tree number P39 is a 17cm dbh Maple Norway that is growing on the backyard of the subject property. This tree is in fair condition and requires a tree protection zone of 2.4m.

Tree number P40 is a 25cm dbh Maple Norway that is growing on the backyard of the subject property. This tree is in fair condition and requires a tree protection zone of 2.4m.

Tree number P41 is a 25cm dbh Cherry Black that is growing on the backyard of the subject property. This tree is in fair condition and requires a tree protection zone of 2.4m.

Tree number P42 is a 39cm dbh Cherry Black that is growing on the backyard of the subject property. This tree is in fair condition and requires a tree protection zone of 3m.

Tree number P43 is a 21cm dbh Pine Eastern White that is growing on the backyard of the subject property. This tree is in fair condition and requires a tree protection zone of 2.4m.

Tree number P44 is a 25cm dbh Maple Norway that is growing on the backyard of the subject property. This tree is in fair condition and requires a tree protection zone of 2.4m.

Tree number P45 is a 65cm dbh Cherry Black that is growing on the backyard of the subject property. This tree is in poor condition and requires a tree protection zone of 4.2m.

Tree number P46 is a 16cm dbh Maple Norway that is growing on the backyard of the subject property. This tree is in fair condition and requires a tree protection zone of 2.4m.

Tree number P47 is a 86cm dbh Beech American that is growing on the backyard of the subject property. This tree is in fair condition and requires a tree protection zone of 5.4m.

Tree number P48 is a 16cm dbh Beech American that is growing on the backyard of the subject property. This tree is in fair condition and requires a tree protection zone of 2.4m.

Tree number P49 is a 15cm dbh Beech American that is growing on the backyard of the subject property. This tree is in fair condition and requires a tree protection zone of 2.4m.

Tree number P50 is a 19, 19cm dbh Beech American that is growing on the backyard of the subject property. This tree is in fair condition and requires a tree protection zone of 2.4m.

Tree number P51 is a 49cm dbh Oak Red that is growing on the backyard of the subject property. This tree is in fair condition and requires a tree protection zone of 3m.

Tree number P52 is a 20cm dbh Cherry Black that is growing on the backyard of the subject property. This tree is in poor condition and requires a tree protection zone of 2.4m.

Tree number P53 is a 20cm dbh Cherry Black that is growing on the backyard of the subject property. This tree is in fair condition and requires a tree protection zone of 2.4m.

Tree number P54 is a 25cm dbh Cherry Black that is growing on the backyard of the subject property. This tree is in fair condition and requires a tree protection zone of 2.4m.

Tree number P55 is a 63cm dbh Butternut that is growing on the backyard of the subject property. This tree is in poor condition and is recommended for removal. This tree will require genetic testing by a Butternut Assessor to confirm hybridity.

Tree number P56 is a 23cm dbh Cherry Black that is growing on the backyard of the subject property. This tree is in fair condition however it is recommended for removal due to development impacts.

Tree number P57 is a 30cm dbh Cherry Black that is growing on the backyard of the subject property. This tree is in fair condition and requires a tree protection zone of 2.4m.

Tree number P58 is a 30cm dbh Maple Norway that is growing on the backyard of the subject property. This tree is in fair condition and requires a tree protection zone of 2.4m.

Tree number P59 is a 19cm dbh Maple Norway that is growing on the backyard of the subject property. This tree is in fair condition and requires a tree protection zone of 2.4m.

Tree number P60 is a 77cm dbh Butternut that is growing on the backyard of the subject property. This tree is in poor condition and requires a tree protection zone of 4.8m. This tree will require genetic testing by a Butternut Assessor.

Tree number P61 is a 51cm dbh Maple Sugar (hard maple) that is growing on the backyard of the subject property. This tree is in fair condition and requires a tree protection zone of 3.6m.

Tree number P62 is a 23cm dbh Maple Norway that is growing on the backyard of the subject property. This tree is in fair condition and requires a tree protection zone of 2.4m.

Tree number P63 is a 20cm dbh Pine Scots that is growing on the backyard of the subject property. This tree is in poor condition and requires a tree protection zone of 2.4m.

Tree number P64 is a 25cm dbh Oak Red that is growing on the backyard of the subject property. This tree is in fair condition and requires a tree protection zone of 2.4m.

Tree number P65 is a 22cm dbh Fir Balsam that is growing on the backyard of the subject property. This tree is in fair condition however it is recommended for removal due to development impacts.

Tree number P66 is a 25cm dbh Cherry Black that is growing on the backyard of the subject property. This tree is in fair condition however it is recommended for removal due to development impacts.

Tree number P67 is a 17cm dbh Cherry Black that is growing on the backyard of the subject property. This tree is in fair condition however it is recommended for removal due to development impacts.

Tree number P68 is a 17cm dbh Cherry Black that is growing on the backyard of the subject property. This tree is in poor condition however it is recommended for removal due to development impacts.

Tree number P69 is a 26cm dbh Cherry Black that is growing on the backyard of the subject property. This tree is in fair condition however it is recommended for removal due to development impacts.

Tree number P70 is a 17cm dbh Maple Norway that is growing on the backyard of the subject property. This tree is in fair condition however it is recommended for removal due to development impacts.

Tree number P71 is a 21cm dbh Ash Green that is growing on the backyard of the subject property. This tree is in poor condition however it is recommended for removal due to development impacts.

Tree number P72 is a 30cm dbh Cherry Black that is growing on the backyard of the subject property. This tree is in fair condition and requires a tree protection zone of 2.4m.

Tree number P73 is a 35cm dbh Maple Norway that is growing on the backyard of the subject property. This tree is in fair condition and requires a tree protection zone of 3.6m.

Tree number P74 is a 27cm dbh Oak Red that is growing on the backyard of the subject property. This tree is in fair condition however it is recommended for removal due to development impacts.

Tree number P75 is a 32cm dbh Cherry Black that is growing on the backyard of the subject property. This tree is in fair condition and requires a tree protection zone of 3m.

Tree number P76 is a 21cm dbh Maple Red (soft maple) that is growing on the backyard of the subject property. This tree is in fair condition and requires a tree protection zone of 2.4m.

Tree number P77 is a 17cm dbh Maple Red (soft maple) that is growing on the backyard of the subject property. This tree is in fair condition and requires a tree protection zone of 2.4m.

Tree number P78 is a 17cm dbh Maple Red (soft maple) that is growing on the backyard of the subject property. This tree is in fair condition however it is recommended for removal due to development impacts.

Tree number P79 is a 42cm dbh Oak Red that is growing on the backyard of the subject property. This tree is in fair condition however it is recommended for removal due to development impacts.

Tree number P80 is a 27cm dbh Maple Red (soft maple) that is growing on the backyard of the subject property. This tree is in fair condition however it is recommended for removal due to development impacts.

Tree number P81 is a 73cm dbh Pine Eastern White that is growing on the backyard of the subject property. This tree is in fair condition however it is recommended for removal due to development impacts.

Tree number P82 is a 22cm dbh Cherry Black that is growing on the backyard of the subject property. This tree is in fair condition however it is recommended for removal due to development impacts.

Tree number P83 is a 73cm dbh Pine Eastern White that is growing on the backyard of the subject property. This tree is in fair condition however it is recommended for removal due to development impacts.

Tree number P84 is a 72cm dbh Pine Eastern White that is growing on the backyard of the subject property. This tree is in fair condition however it is recommended for removal due to development impacts.

Tree number P85 is a 63cm dbh Pine Eastern White that is growing on the backyard of the subject property. This tree is in fair condition however it is recommended for removal due to development impacts.

Tree number P86 is a 79cm dbh Pine Eastern White that is growing on the backyard of the subject property. This tree is in fair condition however it is recommended for removal due to development impacts.

Tree number P87 is a 21, 22cm dbh Japanese Lilac that is growing on the backyard of the subject property. This tree is in fair condition however it is recommended for removal due to development impacts.

Tree number P88 is a 26cm dbh Maple Red (soft maple) that is growing on the backyard of the subject property. This tree is in fair condition and requires a tree protection zone of 2.4m.

Tree number P89 is a 21cm dbh Oak Red that is growing on the backyard of the subject property. This tree is in fair condition however it is recommended for removal due to development impacts.

Tree number P90 is a 29cm dbh Maple Red (soft maple) that is growing on the backyard of the subject property. This tree is in fair condition however it is recommended for removal due to development impacts.

Tree number P91 is a 45cm dbh Walnut Black that is growing on the backyard of the subject property. This tree is in fair condition and requires a tree protection zone of 3m.

Tree number P92 is a 15, 16cm dbh Cedar White that is growing on the backyard of the subject property. This tree is in fair condition however it is recommended for removal due to development impacts.

Tree number P93 is a 53cm dbh Beech American that is growing on the backyard of the subject property. This tree is in fair condition however it is recommended for removal due to development impacts.

Tree number P94 is a 28cm dbh Cedar White that is growing on the backyard of the subject property. This tree is in fair condition however it is recommended for removal due to development impacts.

Tree number P95 is a 22cm dbh Juniper that is growing on the backyard of the subject property. This tree is in fair condition however it is recommended for removal due to development impacts.

Tree number P96 is a 65cm dbh Cherry Black that is growing on the backyard of the subject property. This tree is in fair condition however it is recommended for removal due to development impacts.

Tree number P97 is a 45cm dbh Maple Norway that is growing on the backyard of the subject property. This tree is in fair condition however it is recommended for removal due to development impacts.

Tree number P98 is a 32cm dbh Cedar White that is growing on the front yard of the subject property. This tree is in fair condition however it is recommended for removal due to development impacts.

Tree number P99 is a 33cm dbh Maple Norway that is growing on the front yard of the subject property. This tree is in fair condition however it is recommended for removal due to development impacts.

Tree number P100 is a 25cm dbh Cedar White that is growing on the front yard of the subject property. This tree is in poor condition however it is recommended for removal due to development impacts.

Tree number P101 is a 20cm dbh Apple that is growing on the front yard of the subject property. This tree is in poor condition however it is recommended for removal due to development impacts.

Tree number P102 is a 33cm dbh Birch Paper that is growing on the front yard of the subject property. This tree is in poor condition and requires a tree protection zone of 3m.

Tree number P103 is a 71cm dbh Oak Red that is growing on the front yard of the subject property. This tree is in fair condition and requires a tree protection zone of 4.8m.

Tree number P104 is a 39cm dbh Elm Siberian that is growing on the front yard of the subject property. This tree is in fair condition and requires a tree protection zone of 3m.

Tree number P105 is a 59cm dbh Cherry Black that is growing on the front yard of the subject property. This tree is in poor condition and requires a tree protection zone of 3.6m.

All protective tree hoarding shall be installed prior to commencement of any construction activities as per Town of Oakville specifications.

Tree #	Common Name	Latin Name	DBH (cm)	Height (m)	Crown Reserve (m)	Crown Height (m)	Canopy Cover Area (m)	Health	Structure	TPZ (m)	Site Plan Results
M1	Cedar White	Thuja occidentalis	10, 21, 31	6	4	6	16	fair	fair	3m	preserve
M2	Cedar White	Thuja occidentalis	9, 11, 13, 13, 13	5	4	5	16	fair	fair	2.4m	preserve
МЗ	Cedar White	Thuja occidentalis	11, 13, 13, 14, 16	5	4	5	16	fair	fair	2.4m	preserve
M4	Mulberry White	Morus alba	11, 14	4	3	4	9	fair	poor	2.4m	preserve
N1	Maple Norway	Acer platanoides	22	6	4	4	16	fair	fair	2.4m	preserve
N2	Elm Siberian	Ulmus pumila	10 to 15	7	3	6	9	poor	poor	2.4m	preserve
N3	Juniper	Juniperus virginiana	21	8	4	7	16	fair	fair	2.4m	preserve
N4	Hemlock Eastern	Tsuga canadensis	26, 38	10	6	8	36	fair	fair	3m	preserve
N5	Cherry Black	Prunus serotina	46	15	7	5	49	fair	fair	3m	preserve
N6	Cherry Black	Prunus serotina	54	15	7	5	49	fair	poor	3.6m	preserve
N7	Birch River	Betula nigra	45	12	15	6	225	fair	fair	3m	preserve
N8	Beech American	Fagus grandifolia	50	20	10	8	100	fair	fair	3m	preserve
N9	Pine Eastern White	Pinus strobus	60	20	10	10	100	fair	fair	3.6m	preserve
N10	Cherry Black	Prunus serotina	15	8	4	5	16	fair	fair	2.4m	preserve
N11	Maple Red (soft maple)	Acer rubrum	20	10	4	9	16	fair	fair	2.4m	preserve
N12	Spruce White	Picea glauca	15	6	4	6	16	fair	fair	2.4m	preserve
N13	Maple Red (soft maple)	Acer rubrum	20	10	4	9	16	fair	fair	2.4m	preserve
N14	Pine Eastern White	Pinus strobus	40	20	7	5	49	fair	fair	3m	preserve
N15	Butternut	Juglens cineria	60	19	10	9	100	fair	fair	3.6m	preserve
N16	Maple Red (soft maple)	Acer rubrum	19	9	4	7	16	fair	fair	2.4m	preserve

	7 11 10 0 1	iist neport - 2	00 11001		Drive, C	untille	, Onta				
N17	Ash White	Fraxinus americana	16	15	3	5	9	poor	poor	2.4m	preserve
N18	Beech American	Fagus grandifolia	20	18	5	14	25	fair	fair	2.4m	preserve
N19	Pine Eastern White	Pinus strobus	50	20	7	9	49	fair	poor	3m	preserve
P1	Maple Norway	Acer platanoides	58	14	10	8	100	poor	fair	3.6m	preserve
P2	Maple Sugar (hard maple)	Acer saccharum	101	20	15	14	225	fair	fair	6m	preserve
P3	Yew Canada	Taxus canadensis	13, 15, 15, 20, 20	8	8	8	64	fair	fair	2.4m	preserve
P4	Beech American	Fagus grandifolia	23	11	5	9	25	fair	fair	2.4m	preserve
P5	Beech American	Fagus grandifolia	20	11	5	6	25	fair	fair	2.4m	preserve
P6	Beech American	Fagus grandifolia	27	12	5	6	25	fair	fair	2.4m	preserve
P7	Apple	Malus spp.	37	6	1	4	1	poor	poor	3m	remove
P8	Beech American	Fagus grandifolia	14, 14, 17, 76	18	12	15	144	fair	poor	4.8m	remove
		9	17, 70								
P9	Beech American	Fagus grandifolia	18, 19	12	5	6	25	fair	poor	2.4	preserve
P9 P10	American Beech American	Fagus		12 15	5 7	6 9	25 49	fair fair	poor	2.4 3m	preserve preserve
	American Beech	Fagus grandifolia Fagus	18, 19						·		•
P10	American Beech American Maple Sugar (hard	Fagus grandifolia Fagus grandifolia Acer	18, 19 32	15	7	9	49	fair	poor	3m	preserve
P10	American Beech American Maple Sugar (hard maple) Beech American Beech American	Fagus grandifolia Fagus grandifolia Acer saccharum	18, 19 32 72	15 22	7	9	49 100	fair fair	poor fair	3m 4.8m	preserve
P10 P11 P12	American Beech American Maple Sugar (hard maple) Beech American Beech	Fagus grandifolia Fagus grandifolia Acer saccharum Fagus grandifolia Fagus	18, 19 32 72 64	15 22 18	7 10 12	9 8 6	49 100 144	fair fair poor	poor fair poor	3m 4.8m 4.2m	preserve preserve
P10 P11 P12 P13	American Beech American Maple Sugar (hard maple) Beech American Beech American Pine Eastern	Fagus grandifolia Fagus grandifolia Acer saccharum Fagus grandifolia Fagus grandifolia	18, 19 32 72 64 62	15 22 18 20	7 10 12 10	9 8 6 8	49 100 144 100	fair fair poor fair	poor fair poor poor	3m 4.8m 4.2m 4.2m	preserve preserve preserve
P10 P11 P12 P13 P14	American Beech American Maple Sugar (hard maple) Beech American Beech American Pine Eastern White Beech	Fagus grandifolia Fagus grandifolia Acer saccharum Fagus grandifolia Fagus grandifolia Fagus grandifolia Pinus strobus Fagus	18, 19 32 72 64 62 57	15 22 18 20 24	7 10 12 10 7	9 8 6 8	49 100 144 100 49	fair fair poor fair fair	poor fair poor poor	3m 4.8m 4.2m 4.2m 3.6m	preserve preserve preserve preserve remove
P10 P11 P12 P13 P14 P15	American Beech American Maple Sugar (hard maple) Beech American Beech American Pine Eastern White Beech American Beech	Fagus grandifolia Fagus grandifolia Acer saccharum Fagus grandifolia Fagus grandifolia Fagus grandifolia Pinus strobus Fagus grandifolia Fagus grandifolia Fagus	18, 19 32 72 64 62 57 70	15 22 18 20 24 20	7 10 12 10 7 14	9 8 6 8 8	49 100 144 100 49 196	fair fair poor fair fair fair	poor fair poor poor poor	3m 4.8m 4.2m 4.2m 3.6m 4.2m	preserve preserve preserve preserve remove
P10 P11 P12 P13 P14 P15 P16	American Beech American Maple Sugar (hard maple) Beech American Beech American Pine Eastern White Beech American Beech American Beech American Beech American Beech	Fagus grandifolia Fagus grandifolia Acer saccharum Fagus grandifolia Fagus grandifolia Pinus strobus Fagus grandifolia Fagus grandifolia Fagus grandifolia Fagus grandifolia Fagus grandifolia Fagus	18, 19 32 72 64 62 57 70 20	15 22 18 20 24 20 14	7 10 12 10 7 14 5	9 8 6 8 10 7	49 100 144 100 49 196 25	fair fair poor fair fair fair	poor fair poor poor poor poor poor	3m 4.8m 4.2m 4.2m 3.6m 4.2m 2.4m	preserve preserve preserve preserve remove remove remove

	AIDU	ist neport - 2	05 1103	LVV OOG I	Dilve, C	Jakville	, Onta	110			
P19	Beech American	Fagus grandifolia	62	20	12	9	144	fair	poor	4.2m	remove
P20	Cherry Black	Prunus serotina	16	8	5	4	25	poor	poor	2.4m	remove
P21	Cherry Black	Prunus serotina	30	12	8	6	64	poor	poor	2.4m	remove
P22	Cherry Black	Prunus serotina	26	18	5	8	25	poor	poor	2.4m	remove
P23	Beech American	Fagus grandifolia	18	14	5	6	25	fair	fair	2.4m	remove
P24	Walnut Black	Juglans nigra	62	24	14	12	196	fair	fair	4.2m	preserve
P25	Cherry Black	Prunus serotina	31	14	7	4	49	poor	poor	3m	preserve
P26	Cherry Black	Prunus serotina	24	12	5	8	25	fair	fair	2.4m	preserve
P27	Butternut	Juglens cineria	32	12	3	4	9	poor	poor	3m	preserve
P28	Maple Norway	Acer platanoides	17	10	5	6	25	fair	fair	2.4m	preserve
P29	Birch Yellow	Betula alleghaniensis	22	10	5	4	25	poor	poor	2.4m	preserve
P30	Maple Norway	Acer platanoides	17	8	5	6	25	fair	poor	2.4m	preserve
P31	Pine Eastern White	Pinus strobus	62	24	10	6	100	poor	poor	4.2m	preserve
P32	Pine Eastern White	Pinus strobus	56	22	12	6	144	fair	fair	3.6m	preserve
P33	Maple Sugar (hard maple)	Acer saccharum	35	14	7	8	49	fair	fair	3m	preserve
P34	Cherry Black	Prunus serotina	28	12	5	4	25	fair	poor	2.4m	preserve
P35	Maple Norway	Acer platanoides	16	12	3	6	9	fair	fair	2.4m	preserve
P36	Maple Norway	Acer platanoides	26	14	7	8	49	fair	fair	2.4m	preserve
P37	Cherry Black	Prunus serotina	41	14	7	5	49	fair	fair	3m	preserve
P38	Maple Norway	Acer platanoides	20	10	7	6	49	fair	fair	2.4m	preserve
P39	Maple Norway	Acer platanoides	17	12	5	4	25	fair	fair	2.4m	preserve
P40	Maple Norway	Acer platanoides	25	14	8	7	64	fair	poor	2.4m	preserve
	_										

	AIDO	rist neport - 2	og west	wood i	Drive, C	Jakville	, Onta	110			
P41	Cherry Black	Prunus serotina	25	16	5	8	25	fair	poor	2.4m	preserve
P42	Cherry Black	Prunus serotina	39	18	5	8	25	fair	poor	3m	preserve
P43	Pine Eastern White	Pinus strobus	21	12	3	6	9	fair	fair	2.4m	preserve
P44	Maple Norway	Acer platanoides	25	18	7	9	49	fair	fair	2.4m	preserve
P45	Cherry Black	Prunus serotina	65	22	12	8	144	poor	poor	4.2m	preserve
P46	Maple Norway	Acer platanoides	16	10	5	8	25	fair	fair	2.4m	preserve
P47	Beech American	Fagus grandifolia	86	20	14	12	196	fair	poor	5.4m	preserve
P48	Beech American	Fagus grandifolia	16	14	5	6	25	fair	fair	2.4m	preserve
P49	Beech American	Fagus grandifolia	15	12	5	6	25	fair	fair	2.4m	preserve
P50	Beech American	Fagus grandifolia	19, 19	14	7	7	49	fair	fair	2.4m	preserve
P51	Oak Red	Quercus rubra	49	18	12	9	144	fair	fair	3m	preserve
P52	Cherry Black	Prunus serotina	20	10	5	5	25	poor	poor	2.4m	preserve
P53	Cherry Black	Prunus serotina	20	12	5	4	25	fair	fair	2.4m	preserve
P54	Cherry Black	Prunus serotina	25	14	7	8	49	fair	fair	2.4m	preserve
P55	Butternut	Juglens cineria	63	18	10	9	100	poor	poor	4.2m	remove
P56	Cherry Black	Prunus serotina	23	16	5	6	25	fair	fair	2.4m	remove
P57	Cherry Black	Prunus serotina	30	16	5	5	25	fair	poor	2.4m	preserve
P58	Maple Norway	Acer platanoides	30	15	7	8	49	fair	fair	2.4m	preserve
P59	Maple Norway	Acer platanoides	19	14	7	10	49	fair	fair	2.4m	preserve
P60	Butternut	Juglens cineria	77	20	14	12	196	poor	poor	4.8m	preserve
P61	Maple Sugar (hard maple)	Acer saccharum	51	22	10	12	100	fair	fair	3.6m	preserve
P62	Maple Norway	Acer platanoides	23	15	5	6	25	fair	fair	2.4m	preserve
P63	Pine Scots	Pinus sylvestris	20	12	3	5	9	poor	poor	2.4m	preserve

P64	Oak Red	Quercus rubra	25	16	7	6	49	fair	fair	2.4m	preserve
P65	Fir Balsam	Abies balsamea	22	10	7	9	49	fair	fair	2.4m	remove
P66	Cherry Black	Prunus serotina	25	14	5	6	25	fair	fair	2.4m	remove
P67	Cherry Black	Prunus serotina	17	12	5	6	25	fair	poor	2.4m	remove
P68	Cherry Black	Prunus serotina	17	11	5	6	25	poor	poor	2.4m	remove
P69	Cherry Black	Prunus serotina	26	16	5	6	25	fair	fair	2.4m	remove
P70	Maple Norway	Acer platanoides	17	14	5	6	25	fair	fair	2.4m	remove
P71	Ash Green	Fraxinus pennsylvanica	21	14	8	8	64	poor	poor	2.4m	remove
P72	Cherry Black	Prunus serotina	30	16	10	8	100	fair	fair	2.4m	preserve
P73	Maple Norway	Acer platanoides	35	16	10	8	100	fair	fair	3.6m	preserve
P74	Oak Red	Quercus rubra	27	17	7	7	49	fair	fair	2.4m	remove
P75	Cherry Black	Prunus serotina	32	18	7	6	49	fair	poor	3m	preserve
P76	Maple Red (soft maple)	Acer rubrum	21	16	7	8	49	fair	fair	2.4m	preserve
P77	Maple Red (soft maple)	Acer rubrum	17	12	5	8	25	fair	poor	2.4m	preserve
P78	Maple Red (soft maple)	Acer rubrum	17	12	5	6	25	fair	poor	2.4m	remove
P79	Oak Red	Quercus rubra	42	18	10	9	100	fair	fair	3m	remove
P80	Maple Red (soft maple)	Acer rubrum	27	12	7	9	49	fair	fair	2.4m	remove
P81	Pine Eastern White	Pinus strobus	73	20	12	10	144	fair	poor	4.8m	remove
P82	Cherry Black Pine	Prunus serotina	22	12	5	6	25	fair	poor	2.4m	remove
P83	Eastern White Pine	Pinus strobus	73	20	10	12	100	fair	fair	4.8m	remove
P84	Eastern White	Pinus strobus	72	22	10	12	100	fair	fair	7.8m	remove

		rist Report - 2	69 West	wood	Drive, C	akville	e, Ontai	rio			
P85	Pine Eastern White Pine	Pinus strobus	63	22	12	12	144	fair	fair	4.2m	remove
P86	Eastern White	Pinus strobus	79	22	12	14	144	fair	fair	4.8m	remove
P87	Japanes e Lilac	Syringa reticulata	21, 22	10	7	5	49	fair	poor	2.4m	remove
P88	Maple Red (soft maple)	Acer rubrum	26	12	7	6	49	fair	fair	2.4m	preserve
P89	Oak Red	Quercus rubra	21	16	5	7	25	fair	fair	2.4m	remove
P90	Maple Red (soft maple)	Acer rubrum	29	14	7	7	49	fair	fair	2.4m	remove
P91	Walnut Black	Juglans nigra	45	18	10	9	100	fair	fair	3m	preserve
P92	Cedar White	Thuja occidentalis	15, 16	10	5	9	25	fair	poor	2.4m	remove
P93	Beech American	Fagus grandifolia	53	18	12	9	144	fair	fair	3.6m	remove
P94	Cedar White	Thuja occidentalis	28	14	7	13	49	fair	fair	2.4m	remove
P95	Juniper	Juniperus virginiana	22	4	4	3	16	fair	poor	2.4m	remove
P96	Cherry Black	Prunus serotina	65	20	10	10	100	fair	fair	4.2m	remove
P97	Maple Norway	Acer platanoides	45	16	10	6	100	fair	poor	3m	remove
P98	Cedar White	Thuja occidentalis	32	12	5	12	25	fair	poor	3m	remove
P99	Maple Norway	Acer platanoides	33	14	10	10	100	fair	fair	3m	remove
P100	Cedar White	Thuja occidentalis	25	8	5	6	25	poor	fair	2.4m	remove
P101	Apple	Malus spp.	20	6	5	3	25	poor	poor	2.4m	remove
P102	Birch Paper	Betula papyrifera	33	12	5	4	25	poor	poor	3m	preserve
P103	Oak Red	Quercus rubra	71	20	12	14	144	fair	fair	4.8m	preserve
P104	Elm Siberian	Ulmus pumila	39	14	10	10	100	fair	fair	3m	preserve
P105	Cherry Black	Prunus serotina	59	15	10	8	100	poor	poor	3.6m	preserve

Tree ownership is indicated by the tree naming system, tree names beginning with the letter M are municipally owned, tree names beginning with the letter N are on neighbouring properties within 6m of the property line and tree names beginning with the letter P are privately owned and on the subject property.



The International Society of Arboriculture

Hereby Announces That



Stephen W. Shelton

Has Earned the Credential

ISA Certified Arborist ®

By successfully meeting ISA Certified Arborist certification requirements through demonstrated attainment of relevant competencies as supported by the ISA Credentialing Council





18 March 2000

30 June 2024

ON-0542AT

Expiration Date Certification Number







The International Society of Arboriculture

Hereby Announces That



Stephen W. Shelton

Has Earned the Credential

ISA Tree Risk Assessment Qualification®

By successfully meeting ISA Tree Risk Assessment Qualification certification requirements through demonstrated attainment of relevant competencies as supported by the ISA Credentialing Council



Caitlyn Pollihan
CEO & Executive Director

1 February 2013 Issue Date 31 May 2027 Expiration Date



Limitations of Assessment

It is the policy of Summit SKS Limited to attach the following clause in regards to limitations. This is to ensure that the client is fully aware of what is technically and professionally realistic in the preservation and assessment of trees in the urban environment.

The assessment of the trees in this report has been done in conjunction with and according to accepted arboriculture methods and techniques. These include an examination of the above ground parts of the tree for structural defects, scars, cracks, the overall condition of the visible root structures, the severity and direction of lean (if any), the general condition of the trees and the surrounding environment, external indications of decay such as fungal fruiting bodies, evidence of attack by insects, symptoms of infestation and pathogens, discoloured foliage, and the proximity of potential targets should a tree fail. Except where specifically noted, the trees not cored, probed or climbed and there was no detailed inspection of the root crowns involving excavations, or samples taken to be scientifically tested.

Notwithstanding the recommendations and conclusions presented in this report, it must be acknowledged that trees are living organisms. They are not immune to changes in site conditions, dramatic weather events or seasonal variations in climate. Therefore it should always be recognized that trees are ever evolving and their health and vigour constantly vary over time. While all reasonable efforts have been made to ensure that the subject trees are healthy, no guarantees are offered or implied that these trees or part(s) of any trees will remain intact.

It is professionally and practically impossible to predict with absolute certainty the behaviour of any tree or its component parts under all circumstances and variables. Most trees have the potential for failure under adverse weather conditions and the risk can only be completely eliminated if the tree is removed. inherently, a standing tree will always pose some level of risk. Although every effort has been made to ensure that this assessment is reasonably accurate, trees should be re-assessed periodically. The assessment presented in this report is valid at the time of inspection.

The report is the property of Summit SKS Limited and/or its agents and may not be used until payment is made in full unless written permission is granted to do so. Summit SKS Limited reserves the right to withdraw this report and its recommendations, if any requirements are not met. All details and graphics are copyright of Summit SKS Limited.

On Behalf of Summit SKS Limited

Stephen Shelton, Certified Arborist ON-0542AT

TRAQ 1589





KEY MAPN.T .S.





REVISIONS/SUBMISSION

D A TE DESCRIPTION
1 25/04/2022 1st Submission
2 3 ______
4 ______
5 ______

Certificati





Element Modern Dwellings

MUNICIP ALIT Y

Town of Oakville

Private Residence

269 WESTWOOD DRIVE

MUNICIP AL FILENUMBER #-n/a

CHEET

PROJECT

Tree Protection Plan



