APPENDIX A

Heritage Grant Recommendations 2017		
Property Address	Summary of Approved Works	Recommended Amount
126 Bath Street	Foundation repair	10000
38 Burnet Street	Storm window repair and replacement	2500
293 MacDonald Road	Chimney cap installation and masonry repair	800
66 Second Street	Shore up floor supports in basement	900
66 Second Street	Siding, window sill, and roof repair and replacement (completed)	0
18 Thomas Street	Door replacement and window repair	3500
26 Thomas Street	Wooden wall replacement	7000
187 William Street	Siding, rail, and shutter replacement	2500
295 William Street	Sash window restoration and storm window replacement	5500
1189 Lakeshore Road East	Front door restoration	\$2,200
30 Dunn Street	Window restoration	1700
30 Dunn Street	Exterior painting	2000
30 Dunn Street	Stucco repair	400
30 Dunn Street	Fence repair	0
1150 Dundas Street West	Interior plaster repair, exterior masonry repair, and window repairs	12000
177 King Street	Stone wall repair	0
21 Allan Street	Gazebo repair	5000
167 Reynolds Street	Storm window repair and replacement	4500
24 Thomas Street	Foundation masonary repair	1000
65 Thomas Street	Porch restoration	9000
155 Allan Street	Porch restoration	1000
326 Reynolds Street	Window restoration	5000
332 Palmer Avenue	Exterior stucco	4500
301 William Street	Door and window retrofit	4000
304 Reynolds Street	Siding and front door replacement and shutter addition	5000
		90000