

**Elm Rd. / Munns Creek Property Encroachments**

**1534 Elm Rd.**

**Encroachment Notes:** Current fence installed inside their property. Pool.






**Elm Rd. / Munns Creek Property Encroachments**

**1530 Elm Rd.**

**Encroachment Notes:** Current fence installed inside their property.





**Elm Rd. / Munns Creek Property Encroachments**

**1528 Elm Rd.**

**Encroachment Notes:** Town land fenced in, no debris, slight slope, short cut grass.






**Elm Rd. / Munns Creek Property Encroachments**

**1524 Elm Rd.**

**Encroachment Notes:** Town land fenced in. Pool. Stone landscaping, newly installed shed on patio pavers, garden furniture, slight slope.






## **Elm Rd. / Munns Creek Property Encroachments**

**1520 Elm Rd.**

**Encroachment Notes:** Town land fenced in, no debris, slight slope, short cut grass.





**Elm Rd. / Munns Creek Property Encroachments**

**1518 Elm Rd.**


**Encroachment Notes:** Town land fenced in. Pool. No debris, sloped grade, weeds/rough cut grass.



**Elm Rd. / Munns Creek Property Encroachments**

**1516 Elm Rd.**

**Encroachment Notes:** Town land fenced in. Pool. Gabian retaining wall at property line, sloped grade, weeds/rough cut grass.






**Elm Rd. / Munns Creek Property Encroachments**

**1514 Elm Rd.**

**Encroachment Notes:** Town land fenced in, trampoline, play structure, sloped grade,






## Elm Rd. / Munns Creek Property Encroachments

1510 Elm Rd.

Encroachment Notes: Town land fenced in. Pool. Wood, tree and stone debris, sloped grade at property line.





## **Elm Rd. / Munns Creek Property Encroachments**

**1508 Elm Rd.**

**Encroachment Notes:** Town land fenced in. Pool. Railroad tie retaining wall at property line, metal garden shed, clopped grade, weeds.

